



**american
eurocopter**
an EADS North America Company

AS 365N2/N3 DAUPHIN 2 REVISION STATUS

REVISED: 06-30-10

TYPE OF AIRCRAFT: AS365N2/N3

| <u>MANUAL</u> | <u>REVISION</u> | <u>DATED</u> | <u>RUSH REVISION</u> | <u>DATED</u> |
|-------------------------------------|-----------------|------------------|----------------------|--------------|
| DESCRIPTION & OPERATION MANUAL(DOM) | 22 | 09-51 | | |
| CUSTOMIZED S/N 6364 TO S/N 6461 | 3 | 92-51 | | |
| CUSTOMIZED S/N 6462 & ONWARD | 3 | 95-07 | | |
| MAINTENANCE PROGRAM | | | | |
| N2 | 13 | 08-08-09 | | |
| N2 5.99 | 11 | 08-08-09 | | |
| N3 | 13 | 08-08-09 | | |
| N3 5.99 | 11 | 08-08-09 | | |
| MAINTENANCE MANUAL (MWC) | 23 | 09-51 | | |
| N2 CUSTOMIZED | 3 | 92-51 | 4F | 09-29 |
| N3 CUSTOMIZED | 3 | 95-07 | | |
| MAINTENANCE REPAIR MANUAL (MRR) | 23 | 90-15 | | |
| STORAGE PRESERVATION MANUAL (SPM) | 11 | 08-28 | | |
| ILLUSTRATED PARTS CATALOG (IPC) | 4 | 12-17-09 | | |
| ILLUSTRATED PARTS CATALOG N3 | 9 | 12-17-09 | | |
| TOOL CATALOG (T/C) | 10 | 05-14 | | |
| FAULT ISOLATION (FIM) | 14 | 90-15 | | |
| N2 CUSTOMIZED | 3 | 92-51 | 4A | 09-29 |
| N3 CUSTOMIZED | 3 | 95-07 | | |
| WIRING DIAGRAM MANUAL (WDM) | 20 | 09-32 | | |
| CUSTOMIZED S/N 6364 TO S/N 6461 | 3 | 92-51 | | |
| CUSTOMIZED S/N 6462 & ONWARD | 3 | 95-07 | | |
| MODIFICATION INDEX | 8 | 09-32 | | |
| EUROCOPTER SERVICE BULLETINS | | SEE INDEXES | | |
| EUROCOPTER SERVICE LETTERS | | SEE INDEXES | | |
| AEC MAINTENANCE NOTICES & BULLETINS | | SEE INDEXES | | |
| STANDARD PRACTICES | 31 | 09-29 | 32a | 09-41 |
| FLIGHT MANUAL "N2" | | SEE SEPARATE SRD | | |
| FLIGHT MANUAL "N3" | | SEE SEPARATE SRD | | |
| DVD | 30 | 04-29-10 | | |
| DVD COMPONENT MANUAL | 13 | 05-21-10 | | |

**FOR PUBLICATIONS RELATED TO THE ENGINE, PLEASE APPLY TO THE ENGINE MANUFACTURER.

SERVICE BULLETINS AND SERVICE LETTERS MAILED IN 2010

365 N/N1/N2/N3

REVISED: 06-21-10

AIRFRAME SERVICE BULLETINS

| <u>S/B</u> | <u>DATED</u> |
|---------------------|--------------|
| 00.00.01 REV 1 | 10-16 |
| 00.00.02 | 10-23 |
| EASB 01.00.61 REV 2 | 10-21 |
| ASB 05.00.48 REV 3 | 09-47 |
| ASB 05.00.54 REV 3 | 09-46 |
| ASB 05.00.57 REV 1 | 10-13 |
| ASB 05.00.55 REV 1 | 10-04 |
| 21.00.15 REV 4 | 10-04 |
| 25.01.10 | 10-12 |
| 25.00.44 REV 1 | 10-02 |
| 25.01.06 | 10-02 |
| 25.01.09 | 09-52 |
| 25.00.44 REV 1 | 10-02 |
| 25.00.94 REV 1 | 10-20 |
| 29.00.09 REV 1 | 10-02 |
| 30.00.04 | 10-08 |
| 34.00.29 | 09-48 |
| ASB 34.00.31 | 10-21 |
| 45.00.01 REV 2 | 09-48 |
| 53.00.41 REV 1 | 10-12 |
| 65.00.17 | 10-17 |

SAFETY INFORMATION NOTICES

| <u>I/N</u> | <u>DATE</u> |
|------------------|-----------------|
| 2059-I-00 | 03-22-10 |
| 2077-I-00 | 03-04-10 |
| 2085-I-01 | 12-22-09 |
| 2097-I-24 | 03-22-10 |
| 2103-I-29 | 12-09-09 |
| 2105-S-05 | 11-03-09 |
| 2113-I-22 | 12-07-09 |
| 2117-I-31 | 12-21-09 |
| 2118-S-25 | 12-21-09 |
| 2123-I-34 | 01-07-10 |
| 2124-I-76 | 12-21-09 |
| 2127-I-28 | 01-19-10 |
| 2132-S-26 | 12-22-09 |
| 2134-S-62 | 01-04-10 |
| 2137-I-00 | 03-17-10 |
| 2139-I-21 | 01-21-10 |
| 2143-I-32 | 02-08-10 |
| 2144-I-32 | 02-08-10 |
| 2145-I-28 | 02-18-10 |
| 2147-S-26 R1 | 01-29-10 |
| 2149-S-34 | 02-11-10 |
| 2152-S-00 | 02-23-10 |
| 2153-I-00 | 05-31-10 |
| 2155-I-34 | 05-17-10 |
| 2162-I-00 | 03-24-10 |
| 2162-I-00 | 03-31-10 |
| 2170-S-00 | 04-01-10 |
| 2171-I-29 | 04-13-10 |
| 2172-I-00 | 03-30-10 |
| 2175-I-25 | 04-08-10 |
| 2180-I-05 | 04-09-10 |
| 2197-S-00 | 04-21-10 |
| 2197-S-00 R1 | 06-03-10 |
| 2208-I-52 | 06-14-10 |

